


Lathe Parts



Across

2. Provides angular motion of cutting tool
 4. Has adjustable jaws and holds work piece
 5. Heavy casting which rides on bed ways
 9. Attachment used to cut long tapers
 11. Runs thru headstock and provides rotating motion of work piece

12. Control used to engage feed
 13. Transmits power to apron for feeds
 14. Hardened guides that saddle rides on
- ## Down
1. Saddle and apron assembly
 3. Provides power to apron for threading

6. Holds the feed controls
 7. Provides tool motion perpendicular to spindle axis
 8. Dial that provides for timing of leadscrew for threading
 10. Contains the hand fed quill